


**E 5747**



**Schneidbuchse mit durchgehendem Startloch, ohne Bund**

*Cutting bush with through starting hole without collar*



Mat.: CF-H40S+ (Hartmetall / carbide)

d1	d2	l	Nr. / No.
0.5	5	20.7	E 5747/0,5/ 5 x 20,7
	6		E 5747/0,5/ 6 x 20,7
	7		E 5747/0,5/ 7 x 20,7
1	8	E 5747/1 / 8 x 20,7	
	10	E 5747/1 /10 x 20,7	
2	12	E 5747/2 /12 x 20,7	
	14	E 5747/2 /14 x 20,7	
	16	E 5747/2 /16 x 20,7	
	20	E 5747/2 /20 x 20,7	